



GARY R. HERBERT  
Governor  
GREGORY S. BELL  
Lieutenant Governor

# State of Utah

## DEPARTMENT OF NATURAL RESOURCES

### Division of Oil, Gas & Mining

MICHAEL R. STYLER  
Executive Director

JOHN R. BAZA  
Division Director

### Inspection Report Minerals Regulatory Program October 26, 2011

Reviewed: 

<b>Mine Name:</b> Lost Sheep Mine	<b>Permit Number:</b> S/023/0029
<b>Operator Name:</b> Michael Provstgaard	<b>Inspection Date:</b> October 26, 2011
<b>Inspector(s):</b> Wayne Western	<b>Time:</b> 12:15 -1:30 PM
<b>Other Participants:</b> none	<b>Mine Status:</b> Active

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Re-vegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

#### Purpose of Inspection:

This was a routine inspection.

#### Inspection Summary:

The bond amount is for \$11,400 and is escalated until 2015.

The main road to the site has two gates. There were tire track from an ATV that drove around the first gate. There were tire tracks from the ATV when off at a 90 degree angle at the second gate. Due to the topography the vehicle was unable to access the mine site.

Access to the site is possible from the west. There was no indication that anyone had accessed the site from that direction.

The mine is stable and there is no sign of recent activity. The Operator last reported that mining had occurred in 2006.


Rule R647-3-113.4 requires that the Operator provide written notice if mining is suspended for more than five years. If no mining occurs in 2011 then the Operator must inform the Division of the suspension of mining activities.

R647-3-113.5 states that after five years of suspension the Division may require reclamation. Reclamation is required after a ten year suspension unless otherwise approved by the Board.

**Conclusions and Recommendations:**

The Division should continue to monitor the site.

**Inspector's Signature**

A handwritten signature in dark ink, appearing to read "Wayne Walters", is written over a horizontal line.

WHW:

cc: (OPERATOR)

Jerry Mansfield

O:\M023-Juab\S0230029-LostSheep\inspections\INSP-10262011.doc



Head Frame



Equipment storage area